

LOCAL NOTICE TO MARINERS No. 15 OF 2026

Hinkley Point C Marine Works Offshore Area (East)

Fish Return System Offshore outfall head and tunnel ramp – navigation obstruction

Issued 15/07/26

Mariners are advised that, from 15/07/26 until further notice, the Fish Return System (FRS) outfall head and tunnel ramp will not be visible and unmarked at higher states of tide. The head and ramp is made up of rectangular concrete blocks, the corners of which are in the following positions, in the area shown on the chart extract below:

NW corner	51° 12' 50" N	003° 08' 37" W	dry 3.57m
NE corner	51° 12' 50" N	003° 08' 36" W	dry 3.57m
SE corner	51° 12' 48" N	003° 08' 36" W	depth 1.4m
SW corner	51° 12' 50" N	003° 08' 37" W	depth 1.4m

Location Plan: Q(3)G.6s - Admiralty 1152



Mariners are advised to avoid this area and navigate with caution when approaching/departing the HPC Temporary Jetty. Construction vessels are due to return to this area later this year, at which point this LNTM will be updated. When construction of the FRS is complete, the area will be marked with a buoy pattern, the details of which will be promulgated when confirmed.